

**LONG HOLLOW CIRCLE**



**Hilcorp Energy Company**

**HUBER-RIDDLE 1-27**

**LAT: 37.273156 LONG: -107.727793**

**UNIT J, 2550' FSL & 1500' FEL**

**SEC. 27, T035N, R008W**

**LEASE # FEE**

**API NO. 05-067-07647**

**LA PLATA COUNTY, CO 7273**

**EMERGENCY NUMBER: 505-324-5170 OR 911**

**NO SMOKING**

**NO TRESPASSING**

ASBONWORKS.COM

**Corrective Action:** Maintain equipment and clean up impacted material and dispose per Rule 1002.

Tighten stuffing box, cleaned up and properly disposed of impacted soil.



**Corrective Action** Comply with rule 1003.f, treat/remove weeds

Weeds were removed and disposed of properly





**Corrective Action:** Stormwater controls (ie: BMPs) and erosion controls are needed on revegetating soils until the location is stabilized with desirable perennial vegetation.

Stormwater controls (ie: BMPs) and erosion controls are installed





