

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404080646

Date Received:

02/04/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
General		FarmingtonRegulatoryTechs@hilcorp.com
Shorty, Priscilla	505-324-5188	pshorty@hilcorp.com
Walker, Mandi		mwalker@hilcorp.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001705

Inspection Date: 01/13/2025

FIR Submit Date: 01/21/2025

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326206

Location Name: HUBER-RIDDLE-N35N8W Number: 27NWSE County: _____

Qtrqtr: NWSE Sec: 27 Twp: 35N Range: 8W Meridian: N

Latitude: 37.272966 Longitude: -107.728505

FACILITY - API Number: 05-067-00 Facility ID: 326206

Facility Name: HUBER-RIDDLE-N35N8W Number: 27NWSE

Qtrqtr: NWSE Sec: 27 Twp: 35N Range: 8W Meridian: N

Latitude: 37.272966 Longitude: -107.728505

CORRECTIVE ACTIONS:

1 CA# 201928

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 1002.

Date: 01/28/2025

Response: CA COMPLETED

Date of Completion: 02/03/2025

Operator Comment: Tighten stuffing box, cleaned up and properly disposed of impacted soil. See attached photos.

ECMC Decision: _____

ECMC
Representative:

2 CA# 201929

Corrective Action: Comply with rule 1003.f, treat/remove weeds.

Date: _____

Response: CA COMPLETED

Date of Completion: 02/03/2025

Operator
Comment:

Weeds were removed and disposed of properly. See attached photos

ECMC Decision: _____

ECMC
Representative:

3 CA# 201930

Corrective Action: Stormwater controls (ie: BMPs) and erosion controls are needed on revegetating soils until the location is stabilized with desirable perennial vegetation.

Date: 01/28/2025

Response: CA COMPLETED

Date of Completion: 02/03/2025

Operator
Comment:

Stormwater controls (ie: BMPs) and erosion controls are installed. See attached photos.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 2/4/2025 11:50:09 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404080646	FIR RESOLUTION SUBMITTED
404080678	714001705 Resolved Photos

Total Attach: 2 Files