

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404080850

Date Received:

02/04/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

ENR

719-846-7898

cogcc.evergreen@enrllc.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 710500338

Inspection Date: 09/05/2024

FIR Submit Date: 09/06/2024

FIR Status: _____

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC

Company Number: 10705

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 333697

Location Name: REYNARD-632S66W Number: 34SWSE County: _____

Qtrqtr: SWSE Sec: 34 Twp: 32S Range: 66W Meridian: 6

Latitude: 37.207922 Longitude: -104.763856

FACILITY - API Number: 05-071- -00 Facility ID: 333697

Facility Name: REYNARD-632S66W Number: 34SWSE

Qtrqtr: SWSE Sec: 34 Twp: 32S Range: 66W Meridian: 6

Latitude: 37.207922 Longitude: -104.763856

CORRECTIVE ACTIONS:

1 CA# 198439

Corrective Action: Cleanup impacted soils, Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 10/18/2024

Response: CA COMPLETED

Date of Completion: 02/03/2025

Operator Comment: Impacted soil and location cleaned per rule 608.e

ECMC Decision: _____

ECMC Representative:	
----------------------	--

ECMC Representative:	
----------------------	--

Comment:

Title: Construction Technician Date: 2/4/2025 1:00:26 PM

<u>Document Number</u>	<u>Description</u>
404080850	FIR RESOLUTION SUBMITTED
404080867	Raynard clean up
404080871	Erosion repairs
404080873	Flowline removed

Page 2 of 2