

**TEP Rocky Mountain LLC
Federal RGU 31-32-198
Location ID: 316478**



When replaced additional information is required



Damaged tank label.

TEP Rocky Mountain LLC
 Federal RGU 31-32-198
 Location ID: 316478



Replace when faded and/or illegible

Out of service

TEP Rocky Mountain LLC
Federal RGU 31-32-198
Location ID: 316478



Mislabeled

Disconnected and not in use

**TEP Rocky Mountain LLC
Federal RGU 31-32-198
Location ID: 316478**



Location from Northeast corner

Location from Southeast corner