


TEP Rocky Mountain LLC
Federal RGU 23-35-198
Location ID: 316596



No well sign displayed




Faded and illegible well sign

TEP Rocky Mountain LLC
Federal RGU 23-35-198
Location ID: 316596



Unused equipment



Faded, illegible and conflicting labels

TEP Rocky Mountain LLC
Federal RGU 23-35-198
Location ID: 316596



Debris



Debris

**TEP Rocky Mountain LLC
Federal RGU 23-35-198
Location ID: 316596**



Debris



Stained soil

TEP Rocky Mountain LLC
Federal RGU 23-35-198
Location ID: 316596



Stained soil



Stained soil

TEP Rocky Mountain LLC
Federal RGU 23-35-198
Location ID: 316596



Stained soil



Stained soil

TEP Rocky Mountain LLC
Federal RGU 23-35-198
Location ID: 316596



Stained soil



Debris

**TEP Rocky Mountain LLC
Federal RGU 23-35-198
Location ID: 316596**



Location from North entrance



Location from Southwest corner