

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 513-17

Location ID: 452566



Photo # 4021 From entrance to location




Photo # 4022 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 513-17

Location ID: 452566



Photo # 4023 Location



Photo # 4024 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 513-17

Location ID: 452566



Photo # 4025 Location



Photo # 4026 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 513-17

Location ID: 452566



Photo # 4027 Location



Photo # 4028 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 513-17

Location ID: 452566



Photo # 4029 Location



Photo # 4030 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 513-17

Location ID: 452566




Photo # 4031 Location



Photo # 4032 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 513-17

Location ID: 452566



Photo # 4033 Tank label on frac tank damaged & some info is becoming illegible



Photo # 4034 Fuel container less than 50 ft from multiple wellheads/not in compliance with CECMC rules