

Utah Gas Op Ltd dba Utah Gas Corp
Foundation Creek 7430
Location ID: 316296



Tank berm inadequate



Liner needs repair



Utah Gas Op Ltd dba Utah Gas Corp
Foundation Creek 7430
Location ID: 316296



Location from Northwest entrance



Location from East side