

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/04/2025

Submitted Date:

02/05/2025

Document Number:

713601846

FIELD INSPECTION FORMLoc ID 321208 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 74165

Name of Operator: RENEGADE OIL & GAS COMPANY LLC

Address: 6155 S MAIN STREET #225

City: AURORA State: CO Zip: 80016

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

8 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ingve, Edward	303-680-4725	ed@renegadeoilandgas.com	
ECMC Enforcement		dnr_ecmcenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206231	WELL	TA	04/01/2018	GW	011-05055	CORDES-OBERLANDER 1	RI
255940	GAS PROCESSING PLANT	SI	11/24/2015		-	LAS ANIMAS/BENTS FORT GAS PLANT 255940	RI

General Comment:

This is a follow up of the previous reclamation inspections; #713600923, #713601017, #713601284.
 The corrective actions of the previous inspections have not been completed.
 Non-compliance with the Rules will be referred to enforcement.
 Operator is directed to perform corrective actions outlined on this inspection report immediately.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	There are multiple barrels and tanks with no labeling or signage.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	There are unused supplies and equipment scattered throughout the location. There is unused drilling pipe, tanks, cattleguards, fencing supplies which are not needed for this wellsite or gas plant. The storage sheds onsite are in disrepair with debris and trash stored inside which is a fire hazard. It does not appear equipment has been in use for a long time. All unused equipment, supplies, trash, and debris must be removed. Previous CA was not completed.		
Corrective Action:	Comply with Rule 606.	Date:	
Type	OTHER		
Comment:	Due to the presence of multiple migratory bird nest inside the storage sheds, disturbance of the area may be limited. Operator will need to consult CPW and/or USFWS regarding time restrictions and relocation of nests.		
Corrective Action:	Comply with Rule 210 regarding wildlife protection.	Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
Comment:	There are multiple areas of soil staining observed at the location. There is oily sludge at the base of the tank at the east side of location. All stained soils need to be cleaned up and properly disposed. Based on aerial and ground observations, it appears historical spills occurred at many areas of the location. Therefore the Operator will need to investigate and sample to determine the extent of soil impacts. Previous CA was not completed.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Submit Form 19 to report historic spill of impacted material and Contact ECMC EPS staff per Rule 912.b.			Date:

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	The fence around the Gas Plant equipment and wellsite production equipment is in disrepair. Previous CA was not completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1		Open Top		,

Comment:	There is an open top tank with oily condensate with no wildlife or livestock protections. There are cattle tracks all around the tank indicating that cattle could be drinking out of this tank. Immediate notification was provided to the Operator on the day of inspection.		
Corrective Action:	Immediately Comply with Rule 902.b.	Date:	

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION1002a. FENCING Fail

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS Fail

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION Fail

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? Fail

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? Fail

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? FailProduction areas stabilized ? Fail1003c. Compacted areas have been cross ripped? Fail

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Interim reclamation has been impacted due to unused equipment storage at this location. All disturbed areas must be reclaimed once unused equipment has been removed. Previous CA was not completed.

Corrective Action

Comply with the 1003 interim reclamation rules.

Date _____

Overall Interim Reclamation

Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		There are multiple barrels and containers stored on location with no secondary containment. There are barrels that have leaked out oil and chemicals onto the ground. It appears there have been previous spills from equipment and improper storage. Previous corrective action was not completed.				Date: _____
Corrective Action:		Implement or modify BMPs for improved material handling and spill prevention per Rule 1002.f.(2)B. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. Comply with Rule 1002.f.(2).D				
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
Other possible safety observations include but not limited to: There were multiple wire and electric cords hanging low and on the ground. There was piles of fencing wire that could pose entanglement for livestock or wildlife. There were boards with nails laying on the ground.	CostaR	02/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404082423	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6906118
713601847	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6906116