



BRADENHEAD TEST REPORT

Step 1. Before opening any valves, record all tubing and casing pressures as found.
 Step 2. Collect liquid and gas samples as required; consult Bradenhead Testing and Reporting Instructions and Guidance for field specific Orders at <http://cogcc/reg.html#opguidance>
 Step 3. Conduct Bradenhead test.
 Step 4. Submit Form 17 within 10 days of test. Attach a wellbore diagram if not previously submitted or if wellbore configuration has changed since last wellbore diagram was submitted.
 Step 5. Submit sample analytical results via Form 43.

1. OGCC Operator Number: 88370 3. BLM Lease No: _____
 2. Name of Operator: Timka Resources
 4. API Number: 05-121-09902 5. Multiple completion? Yes No
 6. Well Name: R.A. Wood Trust Number: 1
 7. Location (QtrQtr, Sec, Twp, Rng, Meridian): SESW 17 ... 3 N 51W 6
 8. County Washington 9. Field Name: Hardway
 10. Minerals: Fee State Federal Indian

11. Date of Test: 2-7-25
 12. Well Status: Flowing Shut In Gas Lift Pumping Injection Clock/Intermitter Plunger Lift

13. Number of Casing Strings: Two Three Liner?

14. EXISTING PRESSURES

Record all pressures as found	Tubing: _____ Fm: <u>30</u>	Tubing: _____ Fm: _____	Prod Csg _____ Fm: <u>30</u>	Intermediate _____ Csg: _____	Surf. Csg _____ Csg: <u>0</u>
-------------------------------	--------------------------------	----------------------------	---------------------------------	----------------------------------	----------------------------------

BRADENHEAD TEST

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (Bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals.
 Describe character of flow in "Bradenhead Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper
 Describe fluid type in "Bradenhead Fluid" column: H = Water H2O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None

Buried valve? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:	Bradenhead Fluid:
Confirmed open? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<u>00</u>	<u>30</u>	<input type="checkbox"/>	<u>30</u>		<u>0</u>	<u>N</u>
BRADENHEAD SAMPLE TAKEN? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid	<u>05</u>	<u>30</u>	<input type="checkbox"/>	<u>30</u>		<u>0</u>	<u>N</u>
Character of Bradenhead fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black Other:(describe) <u>None</u>	<u>10</u>	<u>30</u>	<input type="checkbox"/>	<u>30</u>		<u>0</u>	<u>N</u>
	<u>15</u>	<u>30</u>	<input type="checkbox"/>	<u>30</u>		<u>0</u>	<u>N</u>
	<u>20</u>	<u>30</u>	<input type="checkbox"/>	<u>30</u>		<u>0</u>	<u>N</u>
	<u>25</u>	<u>30</u>	<input type="checkbox"/>	<u>30</u>		<u>0</u>	<u>N</u>
	<u>30</u>	<u>30</u>	<input type="checkbox"/>	<u>30</u>		<u>0</u>	<u>N</u>
Instantaneous Bradenhead PSIG at end of test: >							<u>0</u>

INTERMEDIATE CASING TEST

With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals.

Describe character of flow in "Intermediate Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper

Describe fluid type in "Intermediate Fluid" column: H = Water H2O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None.

Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermediate Csg PSIG	Intermediate Flow:	Intermediate Fluid:
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid Character of Intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black Other:(describe) _____ _____	□	□	□	□	□	□	□
	□	□	□	□	□	□	□
	□	□	□	□	□	□	□
	□	□	□	□	□	□	□
	□	□	□	□	□	□	□
Instantaneous Intermediate Casing PSIG at end of test: > _____							

Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: <u>Terrin Pivonta</u>	Title: <u>Agent</u>	Phone: <u>() 970-396-7537</u>
Signed: <u>[Signature]</u>	Title: <u>Agent</u>	Date: <u>2-7-2025</u>
Witnessed By: <u>Todd Pivonta</u>	Title: <u>VP</u>	Agency: <u>Timber Resources</u>