

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 2/11/2025



Location Overview – Photo #06585



Location – Photo #06586

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 2/11/2025



Location – Photo #06590

Location – Photo #06589

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 2/11/2025



Location – Photo #06592


Location – Photo #06591

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 2/11/2025



Weathered/Illegible Wellhead Sign – Photo #06587

Weathered/Illegible Wellhead Sign – Photo #06588

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 2/11/2025



Stored Supplies – Photo #06607



Insufficient Erosion Controls/Site Degradation – Photo #06598

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 2/11/2025



Insufficient Erosion Controls/Site Degradation – Photo #06599



Insufficient Erosion Controls/Site Degradation – Photo #06600

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 2/11/2025



Insufficient Erosion Controls/Site Degradation – Photo #06601



Insufficient Erosion Controls/Site Degradation – Photo #06602

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 2/11/2025



Insufficient Erosion Controls/Site Degradation – Photo #06603



Insufficient Erosion Controls/Site Degradation – Photo #06604

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 2/11/2025



Insufficient Erosion Controls/Site Degradation – Photo #06605



Insufficient Erosion Controls/Site Degradation – Photo #06606

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 2/11/2025



Lease Road Cut Slope Sloughed/No BMPs – Photo #06609



Lease Road Cut Slope Sloughed/No BMPs – Photo #06610

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 2/11/2025



Lease Road Cut Slope Sloughed/No BMPs – Photo #06611