

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404092966

Date Received:

02/13/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10840

Name of Operator: ABUNDANCE ENERGY SERVICES LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Price Andrew

aprice@abundance-energy.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714001763

Inspection Date: 01/24/2025

FIR Submit Date: 01/30/2025

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: ABUNDANCE ENERGY SERVICES LLC

Company Number: 10840

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

### LOCATION - Location ID: 333792

Location Name: JACQUES-N33N8W Number: 27SENW County: \_\_\_\_\_

Qtrqr: SENW Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.076490 Longitude: -107.707860

### FACILITY - API Number: 05-067- -00 Facility ID: 333792

Facility Name: JACQUES-N33N8W Number: 27SENW

Qtrqr: SENW Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.076490 Longitude: -107.707860

### CORRECTIVE ACTIONS:

1 CA# 202217

Corrective Action: Comply with rule 406. install wildlife protections.

Date: 02/06/2025

Response: CA COMPLETED

Date of Completion: 02/06/2025

Operator Comment: Wildlife Covering By the Jaques 1 well head has been repaired.

ECMC Decision: \_\_\_\_\_

Date:

Date of Completion: 02/06/2025

Location signs were up-dated as soon as weather conditions would allow the stickers to adhere to the cold metal sign.

ECMC Decision: \_\_\_\_\_

Comment: See attached for remedial report.

Signed:

Date: 2/13/2025 2:28:12 PM

404092966	FIR RESOLUTION SUBMITTED
404092988	Remedial Report

Page 2 of 2