

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/31/2025

Submitted Date:

02/14/2025

Document Number:

694500758**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
NEIDEL, KRIS 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 95960Name of Operator: WEXPRO COMPANYAddress: P O BOX 45003City: SALT LAKE CITY State: UT Zip: 84145-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stegall, April	307-352-7561	april.stegall@dominionenergy.com	
Russell Ferrell		russell.l.ferrell@dominionenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
489200	SPILL OR RELEASE	AC	02/10/2025		-	Powder Wash Camp Lateral 118	EI

General Comment:

On 1/31/25 ECMC staff, Kris Neidel inspected the spill at the Powder Wash Camp Lateral 118. Weather was 25 degrees and partly sunny at the time of inspection, ground was mostly frozen. The following was observed; partial snow cover, the section of pipe that failed was removed and pipe was repaired by welding in a new segment of pipe, the excavation was still open and pipe exposed, it was reported that the line gathers gas from the field. Corrective actions: demonstrated remaining soils are compliant with Table 915-1. See attached photos.

