

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404099683

Date Received:  
02/19/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
ERIN JOSEPH	970-515-1169	ECMCInspections@Oxy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718200015  
Inspection Date: 01/06/2025 FIR Submit Date: 02/05/2025 FIR Status:

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 328585

Location Name: HSR-CHADIMA-63N66W Number: 14NWNW County:  
Qtrqr: NWN Sec: 14 Twp: 3N Range: 66W Meridian: 6  
W  
Latitude: 40.231699 Longitude: -104.753535

FACILITY - API Number: 05-123-00 Facility ID: 487149

Facility Name: Chadima 4-14/Christy Facility Number:  
Qtrqr: NWN Sec: 14 Twp: 3N Range: 66W Meridian: 6  
W  
Latitude: 40.231699 Longitude: -104.753535

CORRECTIVE ACTIONS:

1 CA# 202361

Corrective Action: Comply with Rules 606.c. and 1003.f. Date: 02/19/2025

Response: CA COMPLETED Date of Completion: 02/19/2025

Operator Comment: no noxious weeds were identified on location. Per Rule 606.c, tumbleweeds originating from plants grown off-location, were identified on location. The excavation is being backfilled which will address the tumbleweeds identified within the excavation and tumbleweeds were removed as shown in the attached photos

ECMC Decision:

ECMC  
Representative:

2 CA# 202362

Corrective Action: Repair and maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by Rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended. the site was not attended at the time of the inspection.

Date: 02/06/2025

Response: CA COMPLETED

Date of Completion: 02/19/2025

Operator Comment: The purpose of the flowline potholes was to identify the location and depth of the flowline. There are no spills or releases associated with the flowline potholes. The fencing associated with the spill/release as required by Rule 913.b(5)B.i was identified as being maintained and preventing access when the site is unattended. The flowline potholes have been backfilled, and the construction fence has been removed as shown in the attached photos.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH

Signed: \_\_\_\_\_

Title: REGULATORY

Date: 2/19/2025 12:47:18 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

404099695	LOCATION PHOTOS
-----------	-----------------

Total Attach: 1 Files