

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404099683

Date Received:
02/19/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

ERIN JOSEPH

970-515-1169

ECMCInspections@Oxy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718200015

Inspection Date: 01/06/2025

FIR Submit Date: 02/05/2025

FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 328585

Location Name: HSR-CHADIMA-63N66W Number: 14NWNW County: _____

Qtrqtr: NWN Sec: 14 Twp: 3N Range: 66W Meridian: 6
W

Latitude: 40.231699 Longitude: -104.753535

FACILITY - API Number: 05-123- -00 Facility ID: 487149

Facility Name: Chadima 4-14/Christy Facility Number: _____

Qtrqtr: NWN Sec: 14 Twp: 3N Range: 66W Meridian: 6
W

Latitude: 40.231699 Longitude: -104.753535

CORRECTIVE ACTIONS:

1 CA# 202361

Corrective Action: Comply with Rules 606.c. and 1003.f.

Date: 02/19/2025

Response: CA COMPLETED

Date of Completion: 02/19/2025

Operator Comment: no noxious weeds were identified on location. Per Rule 606.c, tumbleweeds originating from plants grown off-location, were identified on location. The excavation is being backfilled which will address the tumbleweeds identified within the excavation and tumbleweeds were removed as shown in the attached photos

ECMC Decision: _____

Corrective Action:	Repair and maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by Rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended. the site was not attended at the time of the inspection.
--------------------	--

Date: 02/06/2025

Date of Completion: 02/19/2025

The purpose of the flowline potholes was to identify the location and depth of the flowline. There are no spills or releases associated with the flowline potholes. The fencing associated with the spill/release as required by Rule 913.b(5)B.i was identified as being maintained and preventing access when the site is unattended. The flowline potholes have been backfilled, and the construction fence has been removed as shown in the attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Date: 2/19/2025 12:47:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404099683	FIR RESOLUTION SUBMITTED
404099695	LOCATION PHOTOS

Total Attach: 2 Files