

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404100298

Date Received:

02/19/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Reid, Marta

marta@westernoperating.com

James, Steven

(303) 893-2438

steve@westernoperating.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601794

Inspection Date: 01/14/2025

FIR Submit Date: 01/21/2025

FIR Status: _____

Inspected Operator Information:

Company Name: WESTERN OPERATING COMPANY

Company Number: 95620

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

LOCATION - Location ID: 324797

Location Name: DAWSON A-619S45W Number: 9NENW County: KIOWA

Qtrqtr: NENW Sec: 9 Twp: 19S Range: 45W Meridian: 6

Latitude: 38.424060 Longitude: -102.466500

FACILITY - API Number: 05-061- -00 Facility ID: 212663

Facility Name: DAWSON A Number: 1

Qtrqtr: NENW Sec: 9 Twp: 19S Range: 45W Meridian: 6

Latitude: 38.424060 Longitude: -102.466500

CORRECTIVE ACTIONS:

1 CA# 201909

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: _____

Response: CA COMPLETED

Date of Completion: 01/31/2025

Operator
Comment:

Disturbed area from flowline installation has been graded and prepped for seeding in the Spring. Operator met with ECMC Staff on 1/14/2025 regarding interim reclamation activities; per ECMC request, the graded soils will be seeded and hydro-mulched in April. Additional contaminated soils have been properly disposed of and confirmation samples were collected at the excavation area on 1/31/2025.

ECMC Decision: _____

ECMC
Representative:

2 CA# 201910

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: _____

Response: CA COMPLETED

Date of Completion: 01/15/2025

Operator
Comment:

Wattles have been installed around excavation area and topsoil. Per ECMC direction, wattles have been
trenched into the ground and additional wattles will be placed. Additional wattles around the soil stockpile have
been put into place to prevent wind erosion and transport on 1/15/2025.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and
complete.

Print Name: Amber Barnett

Signed: _____

Title: Compliance Specialist

Date: 2/19/2025 3:48:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document
Number.

<u>Document Number</u>	<u>Description</u>
404100298	FIR RESOLUTION SUBMITTED
404100311	Work Tickets

Total Attach: 2 Files