

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403979142

Date Received:  
02/20/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Heil, John		john.heil@state.co.us
.TEP		COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708904733  
Inspection Date: 10/02/2024 FIR Submit Date: 10/05/2024 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 432702

Location Name: Beaver Creek Frac Pad Number: 11-7-793 County:  
Qtrqtr: NWN Sec: 7 Twp: 7S Range: 93W Meridian: 6  
W  
Latitude: 39.459362 Longitude: -107.823200

FACILITY - API Number: 05-045-00 Facility ID: 433363

Facility Name: Beaver Creek 11-7-793 Number:  
Qtrqtr: NWN Sec: 7 Twp: 7S Range: 93W Meridian: 6  
W  
Latitude: 39.459362 Longitude: -107.823200

CORRECTIVE ACTIONS:

1 CA# 199349

Corrective Action: Comply with CECMC wildlife rules Date: 10/12/2024

Response: CA COMPLETED Date of Completion: 10/22/2024

Operator Comment: Burner exhaust was plugged. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**2** CA# 199350

Corrective Action: All load lines will be capped or plugged

Date: 10/12/2024

Response: CA COMPLETED

Date of Completion: 10/22/2024

Operator Comment: Loadline has been plugged. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #199349: Burner exhaust was plugged. Corrective Action complete.  
CA #199350: Loadline has been plugged. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 2/20/2025 8:29:56 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403979142	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files