

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403979436

Date Received:  
02/20/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
TEP		COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302858  
Inspection Date: 10/03/2024 FIR Submit Date: 10/04/2024 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334795

Location Name: FEDERAL-67S96W Number: 4NWSE County:  
Qtrqtr: NWSE Sec: 4 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.464709 Longitude: -108.110976

FACILITY - API Number: 05-045- -00 Facility ID: 334795

Facility Name: FEDERAL-67S96W Number: 4NWSE  
Qtrqtr: NWSE Sec: 4 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.464709 Longitude: -108.110976

CORRECTIVE ACTIONS:

1 CA# 199315

Corrective Action: Secure equipment to comply with Rule 608.e. Date: 10/11/2024

Response: CA COMPLETED Date of Completion: 10/17/2024

Operator Comment: Loadline has been plugged. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

**2** CA# 199316

Corrective Action: 1) Secure equipment to comply with Rule 608.e.

Date: 10/11/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Loadline has been plugged. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

**3** CA# 199317

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 10/19/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Rill has been repaired, and the roadside ditch has been pulled and reconstructed to allow for water conveyance. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #199315: Loadline has been plugged. Corrective Action complete.  
CA #199316: Loadline has been plugged. Corrective Action complete.  
CA #199317: Rill has been repaired, and the roadside ditch has been pulled and reconstructed to allow for water conveyance. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 2/20/2025 8:47:26 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403979436	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files