

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404101442

Date Received:

02/20/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>CHEVRON</u>		<u>rbucogccinspectionreports@chevron.onmicrosoft.com</u>
<u>Kellerby, Shaun</u>		<u>shaun.kellerby@state.co.us</u>
<u>Andrew Olson</u>		<u>andrewolson@chevron.com</u>
<u>Dawn Bittner</u>		<u>stephaniebittner@chevron.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713400686

Inspection Date: 02/04/2025

FIR Submit Date: 02/07/2025

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 324306

Location Name: SKINNER RIDGE-66S98W Number: 12NWSW County: _____

Qtrqtr: NWS Sec: 12 Twp: 6S Range: 98W Meridian: 6
W

Latitude: 39.544416 Longitude: -108.284212

FACILITY - API Number: 05-045- -00 Facility ID: 324306

Facility Name: SKINNER RIDGE-66S98W Number: 12NWSW

Qtrqtr: NWS Sec: 12 Twp: 6S Range: 98W Meridian: 6
W

Latitude: 39.544416 Longitude: -108.284212

CORRECTIVE ACTIONS:

1 CA# 202435

Corrective Action: Comply with CECMC Storm water rules

Date: 02/22/2025

Response: CA COMPLETED

Date of Completion: 02/10/2025

Operator
Comment:

On Monday, 10 February 2025 material was hauled to 698-12-1 well pad and placed in the erosion that was noted in the inspection report. Added material and berm at the start of the eroded area will keep water from running off the well pad to the west. Additional material added to around tank containment to reduce the amount of water collected at near the tank containment. Water to drain from the tank area to the East away from the area where the washout existed. Photos are attached

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed. Photos are attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dawn Bittner

Signed:

Title: Administrative Assistant

Date: 2/20/2025 1:39:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404101442	FIR RESOLUTION SUBMITTED
404101553	Location photos

Total Attach: 2 Files