

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404013615

Date Received:  
02/21/2025

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708302958

Inspection Date: 10/23/2024

FIR Submit Date: 10/24/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

#### LOCATION - Location ID: 324239

Location Name: GM-66S96W Number: 27SWSE County: \_\_\_\_\_

Qtrqtr: SWSE Sec: 27 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.490788 Longitude: -108.092266

#### FACILITY - API Number: 05-045-00 Facility ID: 324239

Facility Name: GM-66S96W Number: 27SWSE

Qtrqtr: SWSE Sec: 27 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.490788 Longitude: -108.092266

### CORRECTIVE ACTIONS:

1 CA# 200034

Corrective Action: Comply with CECMC General Safety rules.

Date: 10/30/2024

Response: CA COMPLETED

Date of Completion: 11/21/2024

Operator  
Comment:

Ramp installed in cellar for wildlife egress. Corrective Action complete.

ECMC Decision:

ECMC Representative:		
2	CA# 200035	
Corrective Action:	1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.	Date: 11/09/2024
Response:	CA COMPLETED	Date of Completion: 11/21/2024
Operator Comment:	Location and access road have been bladed/graded to increase stabilization. Corrective Action complete.	
ECMC Decision:		
ECMC Representative:		

OPERATOR COMMENT AND SUBMITTAL	
Comment:	CA #200034: Ramp installed in cellar for wildlife egress. Corrective Action complete. CA #200035: Location and access road have been bladed/graded to increase stabilization. Corrective Action complete.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Jordan Veith	Signed: _____
Title: TEP Representative	Date: 2/21/2025 5:24:04 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description

Total Attach: 0 Files