

Storm Water Management and Erosion control

Location Name: TEP Rocky Mountain LLC Dixon Federal Pad (SWNW-23-692) 11A-23-692

Location # 425899



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas. Location is in close
proximity to Rule 411a Surface Water External Buffer.**

Section/Township/Range: 23 6S92



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control

Location Name: TEP Rocky Mountain LLC Dixon Federal Pad (SWNW-23-692) 11A-23-692

Location # 425899



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control

Location Name: TEP Rocky Mountain LLC Dixon Federal Pad (SWNW-23-692) 11A-23-692

Location # 425899



Photo # 7737 Erosion & transport of sediment off location /insufficient BMP's



Photo # 7738 Wattles need maintenance