

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404088274

Date Received:

02/24/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708905589

Inspection Date: 01/22/2025

FIR Submit Date: 01/26/2025

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 413683

Location Name: YOUNBERG Number: SR 43-12 County: _____

Qtrqtr: LOT 3 Sec: 7 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.452158 Longitude: -107.825839

FACILITY - API Number: 05-045- -00 Facility ID: 413683

Facility Name: YOUNBERG Number: SR 43-12

Qtrqtr: LOT 3 Sec: 7 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.452158 Longitude: -107.825839

CORRECTIVE ACTIONS:

1 CA# 201997

Corrective Action: All load lines will be capped or plugged

Date: 02/02/2025

Response: CA COMPLETED

Date of Completion: 01/29/2025

Operator Comment: Load line has been plugged. Corrective Action complete.

ECMC Decision: _____

Corrective Action: Comply with CECMC pressure safety device rules

Response: CA COMPLETED

Date of Completion: 01/29/2025

PRV vent line now complies with ECMC pressure safety device rules. Corrective Action complete.

ECMC Decision: _____

Corrective Action: Comply with CECMC wildlife rules

Response: CA COMPLETED

Date of Completion: 01/29/2025

Hole in separator has been plugged to prevent wildlife entry. Corrective Action complete.

ECMC Decision:

Comment:

CA #201997: Load line has been plugged. Corrective Action complete.
CA #201998: PRV vent line now complies with ECMC pressure safety device rules. Corrective Action complete.
CA #201999: Hole in separator has been plugged to prevent wildlife entry. Corrective Action complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 2/24/2025 6:07:56 AM

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404088274	FIR RESOLUTION SUBMITTED
-----------	--------------------------

ATTACHMENT LIST