

# Inspection Photos

Loc: 485654

Operator: BNL (ENTERPRISE) INC

Inspection Date: 2/21/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the access road. The side of the road needs to be seeded and stabilized. Previous corrective action was not completed.



## Inspection Photos



**Photo 2.** Facing northwest toward the location. Sign posted at entrance. The location has been reduced in size and reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:485654 | Date: 2/21/2025



## Inspection Photos



**Photo 3.** The degraded perimeter silt fence has not been repaired or removed.





## Inspection Photos



**Photo 4.** Facing northwest toward the interim reclamation area. Some of the straw mulch has blown off the seeded soil.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:485654 | Date: 2/21/2025



## Inspection Photos



February 21, 2025  
+37.545889,-104.127497  
Las Animas County  
ECMC

**Photo 5.** Facing northwest at the location. There is a topsoil berm around the perimeter of the pad. Stormwater drainage from the working pad surface will need to be considered.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:485654 | Date: 2/21/2025



## Inspection Photos



**Photo 6.** Facing toward the wellhead.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:485654 | Date: 2/21/2025