

Inspection Photos

Loc: 483886

Operator: BNL (ENTERPRISE) INC

Inspection Date: 2/21/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the access road. The side of the access road needs to be seeded and stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483886 | Date: 2/21/2025

Inspection Photos



Photo 2. Standing at the east side of the location facing east toward the access road. There are loose soils along the road side that must be seeded and stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483886 | Date: 2/21/2025

Inspection Photos



Photo 3. Facing southwest toward the location. The location has been reduced in size and reclaimed. The topsoil pile has been replaced.



Inspection Photos



Photo 4. Facing northwest at the location. Disturbed soils have been seeded and straw mulched. The degraded silt fence still remains and must be removed or reinstalled.



Inspection Photos



Photo 5. Facing west toward the wellsite. There is a topsoil berm around the perimeter of the pad. Stormwater drainage from the working pad surface will need to be considered.



Inspection Photos



Photo 6. Facing toward the southwest side of the location. Some of the straw mulch has blown off the seeded soil.



Inspection Photos



Photo 7. Facing east at the south side of the location.

