

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman Pad 3 11A-30-691

Location ID: 423309



Photo # 9295 From entrance to location



Photo # 9296 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman Pad 3 11A-30-691

Location ID: 423309



Photo # 9297 Location



Photo # 9298 Mechanical Condition - Possible wellhead leak /gas bubbling up through water in cellar (GGU Kaufman 22C-30-691)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman Pad 3 11A-30-691

Location ID: 423309



Photo # 9299 Mechanical Condition - Possible wellhead leak /gas bubbling up through water in cellar (GGU Kaufman 22C-30-691)



Photo # 9300 Mechanical Condition - Possible wellhead leak /gas bubbling up through water in cellar (GGU Kaufman 22C-30-691)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman Pad 3 11A-30-691

Location ID: 423309



Photo # 9301 Mechanical Condition - Possible wellhead leak /gas bubbling up through water in cellar (GGU Kaufman 22C-30-691)

Photo # 9302 Mechanical Condition - Possible wellhead leak /gas bubbling up through water in cellar (GGU Kaufman 22C-30-691)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman Pad 3 11A-30-691

Location ID: 423309




Photo # 9303 Wellhead sign missing required information



Photo # 9304 Wellhead sign missing required information

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman Pad 3 11A-30-691

Location ID: 423309



Photo # 9305 Wellhead sign missing required information




Photo # 9306 Wellhead signs missing required information

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman Pad 3 11A-30-691

Location ID: 423309



Photo # 9307 Wellhead signs missing required information




Photo # 9308 Wellhead sign missing required information