

Inspection Photos

02/24/2025

Operator: BAYSWATER EXPLORATION &
PRODUCTION LLC - 10261

Location ID: 315536

Inspection Doc: 718100268

Rio Blanco County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315536



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south. Desirable perennial vegetative establishment observed throughout the Location and access road, however uniform establishment has not yet been achieved; additional seeding efforts may be necessary to achieve this. Perennial species observed include introduced grasses such as crested and intermediate wheatgrass. Indian ricegrass was also observed though in lower numbers.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315536



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315536



February 24, 2025

Photo 3: Photo taken from the adjacent reference areas for comparison.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315536



Photo 4: Photo taken from the intersection of the lease road and former access road. Photo shows fence is in disrepair. If fence is no longer necessary, it should be removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources