

Inspection Photos

02/24/2025

Operator: SCOUT ENERGY MANAGEMENT LLC
- 10779

Location ID: 314456

Inspection Doc: 718100270

Rio Blanco County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 314456



Photo 1: Photos 1-2 examples showing Location does not appear to be progressing towards 1004.c.(2) revegetation requirements; Location appears to be predominantly bare and exposed soils with sparse perennial vegetative establishment. A follow-up inspection will be conducted during the 2025 growing season to determine if perennial germination is occurring, and whether additional reclamation efforts are required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 314456



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 314456



Photo 3: Photos examples showing stormwater and erosion control BMPs are missing or insufficient. Erosion logs are no longer in proper functioning condition. No other BMPs appears to have been implemented in conjunction with the erosion logs. This is not per good engineering requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 314456



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources