

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2025

Submitted Date:

02/28/2025

Document Number:

710500443

FIELD INSPECTION FORM

Loc ID 480511 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
 Name of Operator: CITATION OIL & GAS CORP
 Address: 14077 CUTTEN RD
 City: HOUSTON State: TX Zip: 77069

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	COGC
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	COGC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480510	TANK BATTERY	AC	08/17/2021		-	Arapahoe Unit Tank Battery Sec. 27	EI
488412	SPILL OR RELEASE	CL	02/05/2025		-	Arapahoe Unit Tank Battery #Sec. 27	EI
489069	SPILL OR RELEASE	AC			-	Arapahoe Unit Tank Battery Sec. 27	EI

General Comment:

This is an Environmental Inspection for the Arapahoe Unit Tank Battery Sec. 27, Spill Facility ID 488412 and Spill ID 489069, Rem # 38819

Inspected Facilities

Facility ID: 480510 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 488412 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 489069 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)
Oily Soil	Piles		
Comment	Impacted soils were stored on location on a plastic liner within a berm. Operator shall manage, store and dispose of soils in accordance with Rule 905.		
Corrective Action			Date: _____

Spill/Remediation:

Comment:	<p>At the time of inspection, there was an open excavation for the remediation of Spill ID 488412, Remediation Project # 38819. ECMC noted Spill ID 489069 was tied to the incorrect Facility ID # ECMC contacted the Operator to update the Facility ID in a Supplemental Form 19</p> <p>The open excavation showed signs of impacted soils and will need further excavated to delineate impacts to soils. Two tanks were removed from the Tank Battery containment and stored onsite.</p> <p>Operator shall continue quarterly reporting until the site meets Table 915-1 standards.</p>		
Corrective Action:			Date: _____

Emission Control Burner (ECB):	_____
Comment:	_____
Pilot:	_____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
All previously assigned COAs and CAs shall apply	sanchezcc	02/28/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500444	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6939678