

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 23-1 PAD)

Location ID: 324018

Date: 02/26/2025



Feb 26, 2025 at 3:35:33 PM
+39.465582,-108.062383 ±2.10m
Parachute



Feb 26, 2025 at 3:40:24 PM
+39.465606,-108.061813 ±5.35m
Parachute

Photo # 5967 Entrance to location

Photo # 5972 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 23-1 PAD)

Location ID: 324018

Date: 02/26/2025



Photo # 5995 NW corner of location



Photo # 5996 SW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 23-1 PAD)

Location ID: 324018

Date: 02/26/2025



Photo # 5997 SE corner of location




Photo # 5998 NE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 23-1 PAD)

Location ID: 324018

Date: 02/26/2025




Photo # 5979 Wildlife hazard



Photo # 5983 Wildlife hazard

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 23-1 PAD)

Location ID: 324018

Date: 02/26/2025



Photo # 5984 Wildlife hazard



Photo # 5985 Wildlife hazard

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 23-1 PAD)

Location ID: 324018

Date: 02/26/2025



Photo # 5991 Open ended load line



Photo # 6008 Open ended poly pipe/wildlife hazard 0.1 miles NW of location off lease road intersection

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 23-1 PAD)

Location ID: 324018

Date: 02/26/2025



Photo # 6010 Open ended poly pipe/wildlife hazard 0.1 miles NW of location off lease road intersection



Photo # 6017 Open ended poly pipe/wildlife hazard 0.1 miles NW of location off lease road intersection