

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8210 From entrance to location



Photo # 8211 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Feb 24, 2025 at 12:21:19 PM
CO

Photo # 8212 Location



Feb 24, 2025 at 12:33:30 PM
CO

Photo # 8213 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8214 Location



Photo # 8215 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8216 Location



Photo # 8217 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Feb 24, 2025 at 1:11:10 PM
CO

Photo # 8218 Location



Feb 24, 2025 at 1:12:41 PM
CO

Photo # 8219 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8220 Open ended load line



Photo # 8221 Open ended load line

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8222 Unused equipment



Photo # 8223 Same unused equipment

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8224 Unused equipment




Photo # 8225 Unused equipment

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8226 Unused equipment



Photo # 8227 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8228 Hole in liner/liner needs maintenance



Photo # 8229 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8230 Hole in liner/liner needs maintenance



Photo # 8231 Hole in liner/liner needs maintenance



Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8232 Holes in liner/liner needs maintenance



Photo # 8233 Holes in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8234 Hole in liner/liner needs maintenance



Photo # 8235 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CIRCLE B LAND 34D-35-692 Pad

Location # 334673



Photo # 8236 Battery lacks required signage