

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 8004 From entrance to location



Photo # 8005 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 8006 Location



Photo # 8007 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 8008 Location



Photo # 8009 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 8010 Location



Photo # 8011 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



Photo # 8012 Location



Photo # 8013 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



**Photo # 9624 From inspection 708903284 conducted on 03/13/2024 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.**



**Photo # 8014 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.**



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



**Photo # 9625 From inspection 708903284 conducted on 03/13/2024 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.**



**Photo # 8015 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.**



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad

Location ID: 335082



**Photo # 9626 From inspection 708903284 conducted on 03/13/2024 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.**



**Photo # 8016 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.**