

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad
Location ID: 334674



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas. Location is approximately 8 yards from Multa Trina Ditch. Location is in close proximity to Freshwater Emergent & Riverine National Wetlands Inventory areas.

Section/Township/Range: 35 6S92W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad
Location ID: 334674



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad
Location ID: 334674



Photo # 8431 Stockpiled soils with no BMP's



Photo # 8432 Stockpiled soils with no BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad
Location ID: 334674



Photo # 8433 Stockpiled soils with no BMP's



Photo # 8434 Stockpiled soils with no BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad
Location ID: 334674



Photo # 8435 Stockpiled soils with no BMP's