

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2025

Submitted Date:

03/03/2025

Document Number:

713601929**FIELD INSPECTION FORM**Loc ID 488167 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10791Name of Operator: WAVETECH HELIUM INCAddress: 1801 BROADWAY SUITE 600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jobe, Patrick		pjobe@wavetechenergy.com	
GENDELMAN, IGOR		igendelman@wavetechenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488167	LOCATION	AC			-	1 Wavetech Wulff Trust 43-5	RI

**General Comment:**

This is a construction inspection at the 1 Wavetech Wulff Trust#43-5 wellsite.  
See attached photos and additional details within this report.

**Location Construction**

Location ID: 488167 CDP: \_\_\_\_\_

Comment: Topsoil was salvaged and stored at the south side of the location. Contractor stated that approximately 9 inches of topsoil had been salvaged at the location.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: The Operator will submit an approved 1202.a.(3). CPW Waiver for the 1 Wavetech Wulff Trust 43-5 Location to ECMC via Form 4 Sundry not less than 30 days prior to the start of construction. It does not appear a CPW waiver was submitted via form 4 Sundry.

Corrective Action: Immediately comply with form 2A COA: 403444544. Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
SLOPE ROUGHENING	Yes	Vehicle Trakcing	No

Comments: Erosion BMPs: At the time of inspection only surface roughening had been performed around the location perimeter.

Other BMPs: Vehicle tracking control practices must be implemented per Rule 1002.f.(2)F.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)  
Comply with Stormwater BMP's per form 2A.

Date: 03/07/202  
5

Comment: Additional BMP's must be installed per form 2A Stormwater BMP's.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601930	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6941306">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6941306</a>