

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404113031

Date Received:

03/03/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17330 PRESTON RD STE 200D-208

City: DALLAS State: TX Zip: 75252

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Bulf. Cathy

cathybulf@gmail.com

Mark Jackson

mwjackson8@gmail.com

Brandon Parks

bparks33@gmail.com

Sanchez, Chris

chris.sanchez@state.co.us

Butler, Brad

butleroil@yahoo.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601872

Inspection Date: 02/10/2025

FIR Submit Date: 02/11/2025

FIR Status: _____

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC

Company Number: 10797

Address: 17330 PRESTON RD STE 200D-208

City: DALLAS State: TX Zip: 75252

LOCATION - Location ID: 484357

Location Name: Red Rocks Number: 1-14 County: LAS ANIMAS

Qtrqtr: NENW Sec: 1 Twp: 30S Range: 55W Meridian: 6

Latitude: 37.465273 Longitude: -103.526247

FACILITY - API Number: 05-071-00 Facility ID: 484674

Facility Name: Red Rocks Number: 1-14

Qtrqtr: NENW Sec: 1 Twp: 30S Range: 55W Meridian: 6

Latitude: 37.465273 Longitude: -103.526247

CORRECTIVE ACTIONS:

1 CA# 202471

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Immediately clean up area. 24-48 hours to implement improved procedures. 1002.f.(2)B.

Date: 12/13/2024

Response: CA COMPLETED

Date of Completion: 02/25/2025

Operator Comment: Rule 912.a, Field personnel cleaned up area on 12/18 as reported on Form 27-I Doc. No. #404048048, photos attached. Additional clean up was delayed due to high winds and below freezing temperatures for the 10 day period 2/11/2025-2/21/2-25; clean up was completed 2/25/25, photos attached. Rule 1002.f.(2)B, Personnel have been instructed in proper materials handling and spill prevention procedures and practices implemented for material handling and spill prevention of materials used, stored, or disposed of that could result in discharges causing pollution of surface waters. An environmental on-site review was conducted in July 2022 did not identify any immediately downgradient waters of the state. Impermeable tarps were placed under the rig and cuttings containment unit, photos attached.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 202472

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention. Immediately clean up area. 24-48 hours to implement improved procedures. 1002.f.(2)B. Comply with permit BMP/COA's.

Date: 12/13/2024

Response: CA COMPLETED

Date of Completion: 02/28/2025

Operator Comment: Rule 912.a, Field personnel cleaned up area on 12/18 as reported on Form 27-I Doc. No. #404048048, photos attached. Additional clean up was delayed due to high winds and below freezing temperatures for the 10 day period 2/11/2025-2/21/2-25; clean up was completed 2/25/25, photos attached. Rule 1002.f.(2)B, Personnel have been instructed in proper materials handling and spill prevention procedures and practices implemented for material handling and spill prevention of materials used, stored, or disposed of that could result in discharges causing pollution of surface waters. An environmental on-site review was conducted in July 2022 did not identify any immediately downgradient waters of the ptate. Impermeable tarps were placed under the rig and cuttings containment unit, photos attached. In compliance with the permit BMP/COA, personnel have reviewed and received training for how spills or releases will be investigated, controlled, and contained; inspection of equipment is permformed daily during operations to detect staining, drips, or leaks that could result in spills; and vehicles are monitored for leaks..

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Desert Eagle Operating (DEO) is working with the ECMC to remediate areas impacted by drill cuttings/reddish soils or E&P Waste. Rule 912.a, Field personnel cleaned up area on 12/18 as reported on Form 27-I Doc. No. #404048048, photos attached. Additional clean up was delayed due to high winds and below freezing temperatures for the 10 day period 2/11/2025-2/21/2-25; clean up was completed 2/25/25, photos attached. Rule 1002.f.(2)B, Personnel have been instructed in proper materials handling and spill prevention procedures and practices implemented for material handling and spill prevention of materials used, stored, or disposed of that could result in discharges causing pollution of surface waters. An environmental on-site review was conducted in July 2022 did not identify any immediately downgradient waters of the state. Impermeable tarps were placed under the rig and cuttings containment unit, see attached Photos-Red Rocks 1-14 FIRR 12-24. DEO has implemented the approved interim reclamation plan for this location and has noted minimal progression. DEO is working with a local third party reclamation company to develop and implement, as soon as possible, a decompaction, reclamation, stabilization, and seed application plan that will provide the highest likelihood of success in this arid area of Colorado.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathy Bulf

Signed: _____

Title: Manager

Date: 3/3/2025 1:46:12 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404113031	FIR RESOLUTION SUBMITTED
404113400	Photos-Red Rocks 1-14 FIRR 12-24 Clean up

404113406	Photos-Red Rocks 1-14 FIRR 02-25 Clean up
-----------	---

Total Attach: 3 Files