



Hilcorp Energy Company

ALLISON UNIT 19
FORMATION DK/MV
LATITUDE N 37.00225
LONGITUDE W 107.5616
NE/SW, 800' FSL & 1849' FWL
SEC.24 T032N R007W
LEASE NO. FEE
API NO. 05-067-05008
LA PLATA COUNTY, COLORADO
EMERGENCY CONTACT (505) 324-5170 OR 911
NO SMOKING NO TRESPASSING

Comment: Rutting observed on the active pad; stabilization/grading is needed to minimize degradation to the active pad.

Corrective Action: Comply with rule 1002f. Install or repair required BMPs.



