

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2025

Submitted Date:

03/03/2025

Document Number:

718700141**FIELD INSPECTION FORM**Loc ID 331795 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 992 S 4TH AVE SUITE 100-461City: BRIGHTON State: CO Zip: 80601**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HARMS, JASON		jharms@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266038	WELL	PR	06/01/2023	OW	123-21315	WICKSTROM 6-5	RI
331795	LOCATION	AC	06/01/2023		-	WICKSTROM-67N59W 6SWNW	RI

General Comment:

This is an Interim Reclamation and Stormwater Inspection for Location ID (331795).

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment observed on location. Refer to attached inspection photos. Return to service or Comply with Rule 606 to remove all unused equipment.			
Corrective Action:				Date:
Type	DEBRIS			
Comment:	Debris and trash observed throughout the location. Refer to attached inspeciton photos. Comply with Rule 606 and remove all debris/trash from the location.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Pump Jack	#			corrective date
Comment:	Stained soil and equipment observed at pumpjack unit. Refer to attached inspection photos.			
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.			Date: 03/08/2025
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	266038	Type:	WELL	API Number:	123-21315	Status:	PR	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	331795	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. A vegetative assessment will be performed at a later date during the active growing season to verify interim reclamation regulations and standards and will therefore remain "In-Process". Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. ECMC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.

Corrective Action _____ Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Inspector Name: Edwardson, Dylan

Comment:	<div></div>	
Corrective Action:	<div></div>	Date <div></div>
Overall Final Reclamation <div></div>	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<div></div>	<div></div>	<div></div>	<div></div>	<div></div>	<div></div>	<div></div>

Comment:

No stormwater erosion issues observed at the time of this inspection.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718700158	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6942816