

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404099158

Date Received:

03/04/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708905253

Inspection Date: 12/11/2024

FIR Submit Date: 12/15/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 439173

Location Name: Youberg RU Number: 44-7 County: _____

Qtrqtr: SESE Sec: 7 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.454841 Longitude: -107.810805

FACILITY - API Number: 05-045-

-00

Facility ID: 439173

Facility Name: Youberg RU

Number: 44-7

Qtrqtr: SESE Sec: 7 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.454841 Longitude: -107.810805

CORRECTIVE ACTIONS:

1 CA# 201086

Corrective Action: Comply with CECMC wildlife rules

Date: 12/22/2024

Response: CA COMPLETED

Date of Completion: 12/19/2024

Operator
Comment:

Hole in separator was plugged to prevent wildlife entry. Corrective Action complete.

ECMC Decision:

ECMC Representative:			
2	CA# 201087		
Corrective Action:		Comply with CECMC pressure safety device rules	Date: <u>12/22/2024</u>
Response:		CA COMPLETED	Date of Completion: <u>12/19/2024</u>
Operator Comment:		Rain cap was installed on blowdown riser. Corrective Action complete.	
ECMC Decision: _____			
ECMC Representative:			

OPERATOR COMMENT AND SUBMITTAL	
Comment:	CA #201086: Hole in separator was plugged to prevent wildlife entry. Corrective Action complete. CA #201087: Rain cap was installed on blowdown riser. Corrective Action complete.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: <u>Jordan Veith</u>	Signed: _____
Title: <u>TEP Representative</u>	Date: <u>3/4/2025 1:24:02 PM</u>

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404099158	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files