

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404115806

Date Received:  
03/04/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

2 CA Completed  
2 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Anthony	gale	tony@kt-res.com

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 715501357

Inspection Date: 03/03/2025

FIR Submit Date: 03/03/2025

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: KT RESOURCES LLC

Company Number: 10775

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

**LOCATION - Location ID: 316141**

Location Name: WRD COUNTY-62N97W Number: 25NESW County: RIO BLANCO

Qtrqr: NESW Sec: 25 Twp: 2N Range: 97W Meridian: 6

Latitude: 40.112209 Longitude: -108.229093

**FACILITY - API Number: 05-103-00 Facility ID: 232228**

Facility Name: WRD COUNTY Number: 25-32

Qtrqr: NESW Sec: 25 Twp: 2N Range: 97W Meridian: 6

Latitude: 40.112209 Longitude: -108.229093

**CORRECTIVE ACTIONS:**

1 CA# 202957

Corrective Action: Determine cause and repair equipment.  
Remove and properly dispose of oily waste and contaminated soil.

Date: 03/19/2025

Response: CA COMPLETED

Date of Completion: 03/04/2025

Operator Comment: Leaking connection on load line was disassembled, repaired, and put back in place. As much Oil/parrafin/doil was removed as possible given the muddy conditions. oil gator was applied. Any remaing stained soil will be cleaned up when it dries out.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 202958

Corrective Action: Reinstall bird protection.

Date: 03/14/2025

Response: CA COMPLETED

Date of Completion: 03/04/2025

Operator  
Comment: Will reinstall bird screen

ECMC Decision:

ECMC  
Representative:

3 CA# 202959

Corrective Action: Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.

Date: 02/12/2024

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator  
Comment: KT has begun its annual calibration of meters, this well is on the list.

ECMC Decision:

ECMC  
Representative:

4 CA# 202960

Corrective Action: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 03/19/2025

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator  
Comment: When it dries out locations and roads will be graded.

ECMC Decision:

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Anthony Gale

Signed:

Title: co-owner

Date: 3/4/2025 8:25:49 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
404115806	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files