

NON-HAZARDOUS WASTE MANIFEST

Weld County USR No.
1MJUSR20-15-0048

PAWNEE WASTE
LLC

Generator's Name and Mailing Address:
Summit Oil + Gas, LLC
PO Box 783038
Park City, UT 84098

Manifest Number:

No. 225243

Bill To Company Name: (if not the Generator)

Waste Profile Number:

Designated Facility Name, Address, and Phone Number:

Pawnee Waste
47368 County Road 118 (970) 222-0803
Grover, CO 80729

Truck / Container No.

16

Truck Type

Pu Tr

Quantity

8

Unit/Wt/Vol

tons

Waste Generating Location or Well Name: AFE#, PO#, Reference#

Castor 7-59 11 Pad

Waste Name or Waste Description:

Contaminated soil Road base
Pea Gravel

Please Check Activity Waste Type:

- Drilling Completions Production
 P&A Midstream
 Industrial Solid Industrial Liquid C&D

Please Check For Additional Services Required:

- After Hours
 Clean Fill PCC Silt Stone
 Container Cleanout Washout

Special Handling Instructions:

Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste

Printed/Typed Name:

Approved by Brent Hullack

Signature:

Date:

Transporter Acknowledgement Receipt of Materials:

Transporter Company Name:

Reaper Roustabout

Transporter's Phone No.:

Printed/Typed Name:

Joseph

Signature:

Joseph

Date:

2/28/25

Discrepancy and Waste Load Rejection Reason: (complete and attach waste rejection form to this manifest)

Facility Owner or Operator Certification: Receipt of waste materials covered by this manifest (except as noted above)

Printed/Typed Name:

KT

Signature:

[Signature]

Date:

2/28/25

Time In:

2:29 PM

Time Out:

3:47 PM