

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2025

Submitted Date:

03/03/2025

Document Number:

718500006**FIELD INSPECTION FORM**Loc ID 406254 Inspector Name: Collins, Kilian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
Nikki Graber		nikki.graber@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Kilian Collins		kilian.collins@state.co.us	
Jeremy Ferrin		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486147	SPILL OR RELEASE	CL	05/29/2024		-	Klein 24-8 Flowline	EI

General Comment:

ECMC received a land owner complaint about an open excavation at the site, complaint document number: 404027970. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type				
Comment:	Site is overgrown with weeds.			
Corrective Action:	Operator shall comply with Rule 606.			Date: 03/17/2025
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Comment:	Operator received closure for this spill on 7/24/24 on document number: 403805446. The remedial excavation is still open.			
Corrective Action:	Operator shall backfill the excavation and reclaim as soon as possible and notify ECMC staff Kilian Collins (kilian.collins@state.co.us) as soon as backfill activities are complete with photo documentation.			Date: 03/17/2025
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 486147 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404112816	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6941676
718500007	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6941665