

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SCOTT-66S92W/25SWSE

Location ID: 335079

Date: 3/11/2025



Location Overview – Photo #07148



Location – Photo #07171

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SCOTT-66S92W/25SWSE

Location ID: 335079

Date: 3/11/2025



Location – Photo #07154



Location – Photo #07161

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SCOTT-66S92W/25SWSE

Location ID: 335079

Date: 3/11/2025



Location – Photo #07155



Location – Photo #07173

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SCOTT-66S92W/25SWSE

Location ID: 335079

Date: 3/11/2025



Location – Photo #07153



Location – Photo #07150

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SCOTT-66S92W/25SWSE

Location ID: 335079

Date: 3/11/2025



Weathered/Illegible Battery Sign – Photo #07147

Faded/Illegible Wellhead Sign – Photo #07172

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SCOTT-66S92W/25SWSE

Location ID: 335079

Date: 3/11/2025



Debris – Photo #07149



Unserviceable Berm Liner – Photo #07157

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SCOTT-66S92W/25SWSE

Location ID: 335079

Date: 3/11/2025



**Unserviceable Berm Liner – Photo #07158**



**Lack of Stabilization – Photo #07151**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SCOTT-66S92W/25SWSE

Location ID: 335079

Date: 3/11/2025



Lack of Stabilization – Photo #07152



Lack of Stabilization/Degradation – Photo #07170