

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404125702

Date Received:

03/13/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10840

Name of Operator: ABUNDANCE ENERGY SERVICES LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Price, Andrew

aprice@abundance-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001761

Inspection Date: 01/24/2025

FIR Submit Date: 01/30/2025

FIR Status: _____

Inspected Operator Information:

Company Name: ABUNDANCE ENERGY SERVICES LLC

Company Number: 10840

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 326237

Location Name: JAQUES-N33N8W Number: 27NWSE County: _____

Qtrqtr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.071680 Longitude: -107.700380

FACILITY - API Number: 05-067- -00 Facility ID: 326237

Facility Name: JAQUES-N33N8W Number: 27NWSE

Qtrqtr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.071680 Longitude: -107.700380

CORRECTIVE ACTIONS:

1 CA# 202214

Corrective Action: Manage (i.e. mow) weed debris to encourage establishment of desirable vegetation and prevent debris dispersal, and conduct additional reclamation/seeding efforts in interim reclamation areas.

Date: _____

Response: CA COMPLETED

Date of Completion: 02/27/2025

Operator Comment: All weed debris has been removed from the project area. All areas with sparse vegetation within the reclamation area have been reseeded and mulched in an effort to establish desirable vegetation.

ECMC Decision: _____

Corrective Action:	Storm water BMPs and erosion controls (ie: ecofiber, straw mulch, erosion control blankets, etc.) need to be installed and maintained on portions of the project area sparse and bare soils until soils are stabilized with desirable perennial vegetation.
--------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Date:

Date of Completion: 02/27/2025

Operator Comment:	All erosional channeling within the project area has been repaired and BMP's installed where needed to help with future success. Slopes have been seeded and mulched in an effort to establish desirable vegetation in these areas.
-------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

ECMC Decision:

Corrective Action:	Update signs per rule 605a.
--------------------	-----------------------------

Date:

Date of Completion: 02/06/2025

Operator Comment:	Location signs were up-dated as soon as weather conditions would allow the stickers to adhere to the cold metal sign.
-------------------	-----------------------------------------------------------------------------------------------------------------------

ECMC Decision:

Comment:	See attachment for Remedial Report.
----------	-------------------------------------

Signed:

Date: 3/13/2025 7:31:46 AM

<u>Document Number</u>	<u>Description</u>
404125702	FIR RESOLUTION SUBMITTED
404125715	Remedial Report

Page 2 of 2