

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2025

Submitted Date:

03/10/2025

Document Number:

718700172

FIELD INSPECTION FORM

Loc ID 427785 Inspector Name: Edwardson, Dylan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10670
Name of Operator: BISON IV OPERATING LLC
Address: 518 17TH STREET SUITE 1800
City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Petrie, Erica		erica.petrie@state.co.us	
,		ops@bisonog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427784	WELL	SI	03/01/2022	OW	123-35118	Pronghorn 11-14-12HZ	RI
427785	LOCATION	AC			-	Pronghorn 11-14-12HZ	RI

General Comment:

[This is an Interim Reclamation and Stormwater Inspection for Location ID \(427785\).](#)

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type			
Comment:	Signs at entrance, wellhead and tank labels do not reflect current operator of record.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	04/07/2025
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		
Date: _____			
Good Housekeeping:			
Type	DEBRIS		
Comment:	Tumbleweed debris observed within equipment. Comply with Rule 606 and remove all debris.		
Corrective Action:			
Date:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment observed near well and within tank battery secondary containment. Comply with Rule 606 and remove all unused equipment.		
Corrective Action:			
Date:			
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
			corrective date
Type: Other	#		
Comment:	Hydrocarbon staining observed throughout the location.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.	Date:	03/15/2025
Type: Other	#		
Comment:	Lid not securely fastened at buried vault. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		
Corrective Action:			
Date:			
Venting:			
Yes/No			
Comment:			
Corrective Action:			
Date:			
Flaring:			
Type			

Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities

Facility ID: 427784 Type: WELL API Number: 123-35118 Status: SI Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 427785 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: CRP

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment This location does not comply with Reclamation rules. Rule 1002.c. states all stockpiled soils shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production operations.
Stockpiled soils on the western portion of the production areas have evidence of undesirable vegetation, animal burrows, and bare/exposed soils.

Corrective Action Comply with Rule 1002.c. Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. A vegetative assessment will be performed at a later date during the active growing season to verify interim reclamation regulations and standards and will therefore remain "In-Process". Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. ECMC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.

Corrective Action _____ Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: CRP _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Date:

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: Date:

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404121907	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952999
718700190	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952978