

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2025

Submitted Date:

03/17/2025

Document Number:

715501426

FIELD INSPECTION FORMLoc ID 316272 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 3 Number of Corrective Actions
- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schroeder, Siera	(719) 723-1542	siera.schroeder@state.co.us	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Engineering, ECMC		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260090	WELL	SI	06/01/2022	GW	103-10133	WRD UNIT GRADY 20-44	SI

General Comment:**ECMC Inspection Report Summary**

On Monday, 03/17/2025, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the WRD Unit Grady 20-44 well, Location #316272, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority, NSO, Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #702502245 on 3/5/24. The following Corrective Actions are unresolved and original due dates remain:

- Gas meter calibration out of date
- Refer to Inspection Photos for observed compliance issues.

While there during normal operations the following compliance issue was observed:

- Inadequate chemical label
- Refer to Inspection Photos for observed compliance issues.

Review of Production Records indicate well is overdue for a Mechanical Integrity Test.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Inadequate label		
Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.	Date:	03/28/2025
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: (800) 288-0560

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration out of compliance.		
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.	Date:	03/16/2024
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on containment		
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate			
Comment:	Unlined earth and metal			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate			

Comment:	Unlined earth and metal		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	260090	Type:	WELL	API Number:	103-10133	Status:	SI	Insp. Status:	SI	
Idle Well										
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:		<div>January 2025 Production Report Shut In - June 2022 *Contact Area Engineer* Well is overdue for Mechanical Integrity Test (MIT). MIT requires 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.</div>								
Corrective Action:		<div>Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.</div>					Date:			04/17/2025
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.				
Corrective Action:						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501427	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6963239