

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2025

Submitted Date:

03/18/2025

Document Number:

713601987**FIELD INSPECTION FORM**Loc ID 308536 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	
Sanchez, Chris		chris.sanchez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273529	WELL	PR	11/24/2013	CBM	071-08184	LORENCITO 13-15-34-66	RI

General Comment:[This is a reclamation inspection at the LORENCITO #13-15-34-66 wellsite.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type			
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			
		<= 1 bbl			
Comment:	There are oil stained soils under the engine skid and at the wellhead that need to be cleaned up.				
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. Rule 1002..(2).D				Date: 04/01/2025

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues were observed during this inspection.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced Water Lined: YES Pit ID: _____ Lat: 37.079030 Long: -104.771590

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:Liner Type: _____ Liner Condition: InadequateComment: There are two holes observed in the liner. The water level is right at the first hole and is leaking out.Corrective Action Pit liner compromised; Comply with rule Rule 910. Reduce fluid level in pit, contact ECMC EPS staff for directives.Date: 03/20/2025**Fencing:**Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date:

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____Comment: This pit does not appear to have permit.Corrective Action Submit an eForm 15 Pit Report to update ECMC records with current information to comply with rule 908.c.Date: 04/08/2025**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601988	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6964212