

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2025

Submitted Date:

03/20/2025

Document Number:

715501444

FIELD INSPECTION FORM

Loc ID: 316335 Inspector Name: Burchett, Kirby On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 13 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 10775
 Name of Operator: KT RESOURCES LLC
 Address: 3381 WESTBROOK LANE
 City: HIGHLANDS State: CO Zip: 80129

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Schroeder, Siera	(719) 723-1542	siera.schroeder@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266494	WELL	SI	03/01/2024	GW	103-10275	ANT HILL UNIT RBC WG 31-42	SI

General Comment:

[ECMC Inspection Report Summary](#)

On Thursday, 03/20/2025, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the Ant Hill Unit RBC WG 31-42 well, Location #316335, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority, NSO, Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. # 702502509 on 3/19/24. All Corrective Actions have been resolved.

While there during normal operations the following compliance issues were observed:

- Faded chemical label.
- Oily waste and staining.
- Gas meter calibrated. Information on card is incorrect.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Faded container label		
Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.	Date:	03/31/2025
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text" value="(800) 255-0560"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	Tank		
Comment:	Leaking equipment at burner. Oily waste on ground below.		
Corrective Action:	Remove and properly dispose of oily waste, stained and/or contaminated soil.		Date: 04/05/2025

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		

Comment:	Calibrated 3/19/25. Operational Technology Service calibrated gas meter. Dated and initialed old contractor card from 2022. Calibration cards need to be accurate at time of calibration. Advised contractor to fill out a new card to be posted at the meter.			Date:	
Corrective Action:				Date:	
Type:	Horizontal Heater Treater	# 1			
Comment:				Date:	
Corrective Action:				Date:	
Type:	Bird Protectors	# 2			
Comment:				Date:	
Corrective Action:				Date:	
Type:	Deadman # & Marked	# 4			
Comment:				Date:	
Corrective Action:				Date:	
Type:	Plunger Lift	# 1			
Comment:				Date:	
Corrective Action:				Date:	
Type:	Ancillary equipment	# 1			
Comment:	Chemical container on containment			Date:	
Corrective Action:				Date:	
Type:	Bradenhead	# 1			
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate			
Comment:	Unlined earth and metal			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		,
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate			
Comment:	Unlined earth and metal			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 266494 Type: WELL API Number: 103-10275 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: January 2025 Production Report
Shut In - March 2024

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
				Material Handling And Spill Prevention		
Ditches						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501445	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6968281