

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/13/2025

Submitted Date:

03/14/2025

Document Number:

713601977**FIELD INSPECTION FORM**Loc ID 487587 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10797Name of Operator: DESERT EAGLE OPERATING LLCAddress: 17330 PRESTON RD STE 200D-208City: DALLAS State: TX Zip: 75252**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bulf, Cathy		cathybulf@gmail.com	
Butler, Brad	972-345-9195	butleroil@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487587	LOCATION	AC			-	Red Rocks 1-09	RI

General Comment:

This is a pre-construction inspection at the Red Rocks #1-09.
 A form 42 notice was submitted which had a construction start date of 3/13/2025.
 No construction had commenced and a new form 42 notice will need to be submitted.

Location Construction

Location ID: 487587 CDP: _____

Comment: It appears the topsoil composition is mostly Dalerose which has a topsoil horizon of at least 5 inches. The topsoil along the constructed access road will need to be salvaged and stored. There was more rocky soils observed at the wellsite but topsoil will need to be segregated to the extent possible and stored. The planned topsoil salvage of <50 cy is not acceptable and additional topsoil salvage and protection will be necessary.

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: A form 42 notice was submitted which had a construction start date of 3/13/2025. No construction had commenced and a new form 42 notice will need to be submitted no less than 2 days prior to commencement of construction. If any plans change then the Operator will need to contact the ECMC reclamation specialist in advance.

Corrective Action: Comply with Rule 406.b.

Date: 03/14/2025

Wildlife BMPs:**Comment:** _____

Corrective Action: _____

Date: _____

Comment: _____**Corrective Action:** _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404128117	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6959624
713601978	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6959608