

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad

Location # 322442



Photo # 6243 From entrance to location



Photo # 6244 Location



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad

Location # 322442



Photo # 6245 Location



Photo # 6246 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad

Location # 322442



Photo # 6247 Location



Photo # 6248 Location



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad

Location # 322442



Photo # 6249 Location



Photo # 6250 Unused hoses near wellhead



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad

Location # 322442



Photo # 6251 Open ended load line



Photo # 6252 Operator phone # on tank label is disconnected & not in service/not in compliance with CECMC rules

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad

Location # 322442



Photo # 6253 Operator phone # on tank label is disconnected & not in service/not in compliance with CECMC rules



Photo # 6254 Operator phone # on sign at entrance to location is disconnected & not in service & sign lacks emergency services #



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad

Location # 322442



**Photo # 6255 Tank battery lacks required signage**



**Photo # 6256 Middle tank lacks required labeling**

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad

Location # 322442



Photo # 6257 Unused hose