



Multiple excavations remain open. Orange construction fencing has been installed around the excavations but has fallen. Multiple soil stockpiles are visible on location.




Soil stockpiles; BMPs of stockpile in foreground are adequate.



Areas of soil with gray staining are visible adjacent to an excavation.





Areas of gray staining are visible in soil stockpile and its berm; a liner was not present and BMPs are inadequate.





Orange construction fencing no longer encompasses the entire perimeter of the excavation.
 Weather conditions are windy.





Approximate location of Spill ID 482130. No environmental impacts are visible in situ at the pictured excavation.

