

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2025

Submitted Date:

03/25/2025

Document Number:

713602019

**FIELD INSPECTION FORM**

Loc ID 487587 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10797  
 Name of Operator: DESERT EAGLE OPERATING LLC  
 Address: 17330 PRESTON RD STE 200D-208  
 City: DALLAS State: TX Zip: 75252

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Butler, Brad	972-345-9195	butleroil@yahoo.com	
Bulf, Cathy		cathybulf@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487587	LOCATION	AC			-	Red Rocks 1-09	CI

**General Comment:**

This is a construction inspection at the Red Rocks #1-09 location.  
 See all comments and attached photos for inspection observations.

**Location Construction**

Location ID: 487771 CDP: \_\_\_\_\_

**Comment:** Topsoil was salvaged along the access road and at the location. Near the location was large rocks at the surface and soils appeared to be sufficiently salvaged until too much rock was encountered. The piles were tracked for temporary stabilization. Topsoil piles will need to be seeded if stored for more than 6 months.

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** Vegetation removal has occurred before the nesting period for migratory birds (April 1 to August 31).

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
	No		No

**Comments:** Erosion BMPs: At the time of inspection there were no stormwater BMP's installed at the location. Stormwater controls need to be installed prior to construction.

Other BMPs: \_\_\_\_\_

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C **Date:** 03/28/2025

5

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713602020	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974197">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974197</a>