

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2025

Submitted Date:

03/25/2025

Document Number:

715501461

FIELD INSPECTION FORM

Loc ID 314393 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10779
 Name of Operator: SCOUT ENERGY MANAGEMENT LLC
 Address: 13800 MONTFORT DRIVE SUITE 100
 City: DALLAS State: TX Zip: 75240

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Saint, John		jsaint@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Christian, Cody		Cody.Christian@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228637	WELL	PR	01/01/2024	OW	103-05593	LEVISON 2	PR

General Comment:

[ECMC Inspection Report Summary](#)

On Tuesday, 03/25/2025, Compliance Inspector Kirby Burchett, completed a field inspection and audit at Scout Energy Management LLC on the Levison 2 well, Location #314393, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations no compliance issues were observed.

No follow up inspection is required.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	(970) 675-3700		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

				corrective date
Type: Bradenhead	# 1			
Comment:				
Corrective Action:		Date:		
Type: Other	# 1			
Comment:	Wellhead tree			
Corrective Action:		Date:		
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 228637 Type: WELL API Number: 103-05593 Status: PR Insp. Status: PR

Producing Well

Comment: [January 2025 Production Report](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501462	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974452